ASBESTOS ASSES. / SURVEY

H-K Building #: 42

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/24/89 Inspector: MARK VOTH

Building Number: 42 Building Name: POS

SEATTLE, WASHINGTON 98134

Building Type: ADVERTISE Year Constructed: 1949

******* AREA NUMBER: 01	2: 01 AREA DESCRIPTION: 1st Floor-Ceiling				AREA AVERAGE % ASBESTOS: 1%						********		
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	YTTTHAUP	UNITS OF MEASURE	PIPE ID		PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS	
throughout	01-356313 01-356314 01-356315 01-356316 01-356317 01-356318 01-356319	2% 2% 0% 2% 0% 2% 0%	trowelled acoustical plaster	OMD	6075 s	q.ft.		57 57 57 57 57 57 57	11 11 11 11	\$65,974	\$13,183	\$79,157	
AREA COMMENTS						Γ	AREA # 01	TOT	AL	\$65,974	\$13,183	\$79,157	

The material is in good to fair condition with minor contact and water damage. The material is approximately 8° to 10° from the floor. At a minimum, it is recommended that the material be repaired and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a high traffic area.

******** AREA NUMBER: 02 AREA DESCRIPTION: 2nd floor-Ceiling				AREA AVERAGE	4	****				
LOCATION OF THE MATERIAL	SAMPLE NUMBER ASS	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
southwest room-throughout east room-north & south ends	02-356320 29 02-356321 49 02-356322 49 02-356323 39 02-356324 29		OMD OMD	150 sq.ft. 900 sq.ft.		57 57 57 57 57 57	11 11 11	\$518 \$3,105		\$755 \$4,527
central area-throughout east room-central third			OMD OMD	3900 sq.ft. 450 sq.ft.						

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 79

06/09/89

ASBESTOS ASSES SURVEY

H-K Building #: 42

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/24/89 Inspector: MARK VOTH Building Number: 42 Building Name: POS

SEATTLE, WASHINGTON 98134

Building Type: ADVERTISE Year Constructed: 1949

AREA COMMENTS

AREA # 02 TOTAL \$1,659 \$5,282 \$3.623

The material is in good to fair condition with minor contact and water damage. The material is approximately 8' to 10' from the floor. At a minimum, it is recommended the material be repaired and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a high traffic area.

> \$14,842 BUILDING # 42 TOTAL \$69.597 \$84,439

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 80

06/09/89

ASBESTOS ASSES

SURVEY

H-K Building #: 43 Project Number: 0980193E

Date Inspected: 03/28/89
Inspector: VOTH & BAXTER

Building Number: 43
Building Name: NEW WAREHOUSE
SEATTLE, WASHINGTON 98134
Building Type: WAREHOUSE
Year Constructed: 1983

******* AREA NUMBER: 01	AREA DESC	AREA DESCRIPTION: 1st floor-Mezzanine-Ceiling			·	AREA AVE	X.	*****				
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	YTITHAUP	UNITS OF	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
throughout	01-356310 01-356311 01-356312	0% 0% 0%	drop or lay-in panel	OMG	3700 s	q.ft.						
AREA COMMENTS							AREA # 01	тот	AL	\$(\$0	
					•	BUIL	DING # 43	тот	AL	\$0	\$0	

ASBESTOS ASSES SURVEY

H-K Building #: 45

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/29/89 Inspector: C. BAXTER Building Number: 45

Building Name: BRIDGE

SEATTLE, WASHINGTON 98134

Building Type: WALKWAY
Year Constructed: UNKN

******* AREA NUMBER: 01	· AREA DESC	RIPTIO	N: 1st Floor-Bridge		AREA AVERAGE	K	*******				
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP		REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
east & west length of tunnel	00-356714	40%	pipe covering	OMA	250 ft. 10 in. 0.D	LPS/R	25	111	\$4,718	\$3,493	\$8,211
east & west length of tunnel	00-356714	40%	pipe covering	AMO	80 ft. 6 in. O.D.	HPS/R	25	111	\$1,038	\$649	\$1,687
east & west length of tunnel	00-356714	40%	pipe covering	OMA	250 ft. 12 in. 0.D	HPS/R	25	111	\$5,505	\$4,233	\$9,738
east & west length of tunnel	00-356714	40%	pipe covering	OMA	4 ft. 4 in. 0.D.	HPS/R	25	111	\$36	\$22	\$58
east & west length of tunnel	01-356715	60%	mjp on pipe covering	OMA	4 4 in. O.D.	HPS/R	25	111	\$112	\$62	\$174
east & west length of tunnel	01-356715	60%	mjp on pipe covering	OMA	8 12 in. O.D.	HPS/R	25	1111	\$607	\$379	\$986
east & west length of tunnel	01-356715	60%	mjp on pipe covering	OMA	11 6 in. O.D.	HPS/R	25	111	\$425	\$250	\$675
east & west length of tunnel	01-356715	60%	mjp on pipe covering	OHA	6 10 in. O.D.	LPS/R	25	111	\$376	\$235	<u>\$6</u> 11
- -	01-356716	60%					25	111			
	01-356717	60%	1				25	1111			
east & west length of tunnel	02-356718	10%	mjp on non-suspect pipe cover	AMO	2 4 in. O.D.	HPS/R	25	1111	\$56	\$31	\$87
- '	02-356719	20%	1 "					1111			
•	02-356720	10%					25	111			
east & west length of tunnel	03-356727	0%	pipe covering	OMA	250 ft. 10 in. 0.D	PL					

AREA COMMENTS

AREA # 01 TOTAL \$12,873 \$9,354 \$22,227

The materials are in good condition with minor contact and water damage. The materials are approximately 4' to 9' from the floor. At a minimum, it is recommended that the materials be repaired, then monitored under a maintenance program. If removal is planned, gross removal procedures are recommended. This appears to be a high traffic area.

0%

03-356728 03-356729

BUILDING	#	45	TOTAL	\$12,873	\$9,354	\$22,227

*** GRAND TOTAL \$694,153 \$465,441 \$1,159,594